


LC105

LC105		
Torch (Hand 7.5m)	(1pc)	PTH-101A-CX-7M5A
Torch (Hand 15m)	(1pc)	PTH-101A-CX-15MA
Handle	(1pc)	W0300609R
Head	(1pc)	W0300618R
Insulation Kit	(blister 1pc)	W03X0893-71R
Cable (7.5m)	(1pc)	W0300620R
Cable (15m)	(1pc)	W0300622R
Connector	(1pc)	W03X0934-8R



	Electrode (blister 5pcs)		Gas Distr. (blister 2pcs)	Tip (blister 5pcs)		Retaining Cap (blister 1pc)	Spacer (blister 2pcs)		Shield Cap (blister 2pcs)			
Cutting process												
40A	W03X0893 -60A		W03X0893 -70R	W03X0893 -61A		W03X0893 -66A	W03X0893 -14R	W03X0893 -68A				
60A	W03X0893 -60A		W03X0893 -70R	W03X0893 -62A		W03X0893 -66A	W03X0893 -14R	W03X0893 -68A				
80A	W03X0893 -60A		W03X0893 -70R	W03X0893 -63A		W03X0893 -66A	W03X0893 -14R	W03X0893 -68A				
100A	W03X0893 -60A		W03X0893 -70R	W03X0893 -64A		W03X0893 -66A	W03X0893 -14R	W03X0893 -68A				
Contact 40A	W03X0893 -60A		W03X0893 -70R	W03X0893 -61A		W03X0893 -66A				W03X0893 -67A		
Contact 60A	W03X0893 -60A		W03X0893 -70R	W03X0893 -62A		W03X0893 -66A				W03X0893 -67A		
Contact 80A	W03X089 3-60A		W03X0893 -70R	W03X0893 -63A		W03X0893 -66A				W03X0893 -67A		
Contact 100A	W03X089 3-60A		W03X0893 -70R	W03X0893 -64A		W03X0893 -66A				W03X0893 -67A		
Ext Contact 40A		W03X0893 -57A			W03X0893 -58A	W03X0893 -66A					W03X0893 -74A	
Ext Contact 60A		W03X0893 -57A			W03X0893 -59A	W03X0893 -66A					W03X0893 -74A	
Ext Contact 80A		W03X0893 -57A			W03X0893 -72A	W03X0893 -66A					W03X0893 -74A	
Ext Contact 100A		W03X0893 -57A			W03X0893 -73A	W03X0893 -66A					W03X0893 -74A	
Gouging	W03X0893 -60A		W03X0893 -70R	W03X0893 -65A		W03X0893 -66A						W03X0893 -69A